




序号	报告编号	发布日期	结论	影像资料	
42	GX-B1574/20-2-25065	2025. 12. 9	所检项目合格。		
43	GX-B1309/21-2-25022	2025. 12. 11	所检项目合格		

44	GX-B1500/21-2-25086	2025. 12. 11	综合判定：合格	
45	GX-B1500/21-2-25087	2025. 12. 11	综合判定：合格	


46	GX-B1500/21-2-25088	2025. 12. 11	综合判定：合格	
47	GX-B1499/23-2-25099	2025. 12. 11	除吨水百米电耗外， 其余所检项目合格。	



48	GX-B1499/23-2-25100	2025. 12. 11	除吨水百米电耗外， 其余所检项目合格。			
49	GX-B1499/23-2-25101	2025. 12. 11	除吨水百米电耗外， 其余所检项目合格。			

50	GX-B1322/21-2-25478~25479	2025. 12. 11	本次共检验电力电缆2条，2条所检项目合格。 。	
51	GX-B1350/21-2-25051	2025. 12. 11	本次共检接地装置2处，2处接地装置所检项目合格。	

52	GX-B1451/20-2-25826~25833	2025. 12. 11	本次共检高压开关柜8台，8台所检项目合格。 。	
53	GX-B1313/21-2-25274~25275	2025. 12. 11	本次共检电力变压器2台，2台所检项目合格。 。	



54	GX-B1329/21-2-25239~25240	2025. 12. 11	本次共检氧化锌避雷器2组，2组所检项目合格。	 <p>2025.12.9</p>
55	GX-B1598/24-2-25308	2025. 12. 12	实测钢丝绳有效截面 积损失百分比最大为 0.74%，小于5%为正常 。	 <p>2025/11/28</p>

56	GX-B1598/24-2-25309	2025. 12. 12	实测钢丝绳有效截面积损失百分比最大为0.67%，小于5%为正常。	
57	GX-B1598/24-2-25310	2025. 12. 12	实测钢丝绳有效截面积损失百分比最大为0.83%，小于5%为正常。	



58	GX-B1598/24-2-25311	2025. 12. 12	实测钢丝绳有效截面 积损失百分比最大为 1.01%，小于5%为正常 。	 A photograph showing two workers in red safety suits and helmets. One worker is in the foreground, looking towards the camera, while the other is slightly behind him, looking down at a structure. The background shows a metal framework. A date stamp '2025/11/28' is visible in the bottom right corner of the photo.
59	GX-B1304/21-2-25025	2025. 12. 15	综合判定：合格。	 A photograph showing three workers in safety gear (two in red, one in dark blue) standing on a green platform or walkway. They are in an industrial setting with large blue pipes or tanks in the background. A date stamp '2025/11/26' is visible in the bottom right corner of the photo.