





序号	报告编号	发布日期	结论	影像资料
43	GX-B1345/21-9-25005	2025.12.24	1、矿井需要风量：5817m3/min; 布置 2 个采煤工作面、4 个掘进工作面; 2、矿井总进风量：6151m3/min; 3、矿井总回风量：6475m3/min; 4、矿井等积孔：3.02m2; 5、矿井有效风量率：87.7%; 6、矿井外部漏风率：4.9%。	
44	GX-B1342/21-9-25011	2025. 12. 25	1. 矿井总进风量： 5675.4 m3/min; 2. 矿井总回风量： 5942.4 m3/min; 3. 全系统计算阻力 值：2460.04 Pa; 4. 全系统测定阻力 值：2406.4 Pa; 5. 矿井等积孔： 2.56m2。	

45	GX-B1340/25-9-25103	2025.12.29	合格。	 A photograph showing three workers in safety gear (hard hats, jackets) standing in front of a large, red industrial machine, likely a steam boiler or engine. The machine has a warning sign with a red and black striped pattern. The date stamp in the bottom right corner of the photo reads "2025年12月30日".
46	GX-B1371/21-9-25044	2025年12月30日	<p>存在问题： 1、监测监控设备未定期进行调校。 2、无传感器调校记录表。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。</p>	  Two photographs. The left photo shows a worker in an orange safety suit and red hard hat standing in a dark, industrial environment, possibly a tunnel or underground facility. The date stamp in the bottom right corner of the photo reads "2025年12月23日". The right photo shows a worker sitting at a desk in a control room, operating multiple computer monitors. The date stamp in the bottom right corner of the photo reads "2025年12月23日".

47	GX-B1341/24-9-25200	2025. 12. 30	综合判定：合格。	
48	GX-B1341/24-9-25201	2025. 12. 30	综合判定：合格。	

49	GX-B1341/24-9-25203	2025. 12. 31	综合判定：合格。	
----	---------------------	--------------	----------	---