

序号	报告编号	发布日期	结论	影像资料
1	GX-B1539/22-Y-25074	2026年1月6日	所检项目合格。	 A photograph showing two workers in safety gear standing next to a large yellow wheel loader. The loader has 'SANY' branding on its side. The date '2025/12/20' is visible at the bottom right of the photo.
2	GX-B1521/20-Y-25010	2026年1月6日	所检项目合格。	 A photograph showing three workers in safety gear standing near a yellow excavator on a snowy construction site. The date '2025/12/20' is visible at the bottom right of the photo.

3	GX-B1521/20-Y-25011	2026年1月6日	所检项目合格。	
4	GX-B1417/22-Y-25004	2026年1月6日	综合判定：合格。	

5	GX-B1424/20-Y-25003	2026.1.6	依据NB/T 10176-2019 单轨吊车综合判定合 格；依据MT/T 220- 1990 尾气所检项目合 格。	 2025.12.27
6	GX-B1424/20-Y-25003	2026.1.6	依据NB/T 10176-2019 单轨吊车综合判定合 格；依据MT/T 220- 1990 尾气所检项目合 格。	